



URGENT: VOLU	NTARY FIELD SAFETY CORRECTIVE ACTION
Description	Specific lots of DAILIES TOTAL1® and TOTAL 30® contact lenses
Product Reference	DAILIES TOTAL1®, TOTAL 30®

August 13, 2024

## OC VISION Kristīne Detkova

Dear Valued Customer.

Alcon has initiated a Voluntary Field Safety Corrective Action for specific lots of DAILIES TOTAL1® and TOTAL 30® contact lenses. We identified an isolated quality issue with a material supplied by a third-party vendor that was used in the production of these specific contact lens lots at a single manufacturing site. As a result, the identified contact lens lots may not meet Alcon quality and/or performance standards for the entirety of their labeled shelf life.

The contact lenses from the identified lots are not expected to cause an increased risk to the wearer. As with any contact lens, there is a remote likelihood that wearing a lens from the identified lots may lead to temporary issues such as irritation, redness, or blurred vision. These symptoms typically resolve after lens removal and/or replacement (as directed in the patient leaflet).

We ask that you stop any further distribution of contact lenses from the identified lots and request that you contact any eye care practitioners, patients, or others to whom you have distributed the identified lots.

Alcon is committed to delivering outstanding product quality and customer service, and we regret the inconvenience caused by this action.

Sincerely,

Sanja Banek Babic

Banek
Babic, Sanja

Oligitally signed by Banek Babic, Sanja
Ditt. cm-Banek Babic, Sanja
Ditt. c

Regulatory affairs associate director CSEEC

Ref. 2024.016 Page 1 of 4



6201 South Freeway Fort Worth, Texas 76134-2099 www.alcon.com

According to our records, the following contact lens lots have been shipped to your firm and are affected by this Field Safety Corrective Action :

Table 1: Affected conta  Description	Batch	Quantity	
DAILIES TOTAL 1 30P 850 141 -01.50	N1275788	56	Delivery
DAILIES TOTAL 1 5T 850 141 -01.50	N1275795	6	1616723890
DAILIES TOTAL 1 5T 850 141 -01.50	N1275795	-	1614881416
DAILIES TOTAL 1 30P 850 141 -03.25	N1275796	15	1617476254
DAILIES TOTAL 1 30P 850 141 -03.75	N1275799	41	1616250441
DAILIES TOTAL 1 30P 850 141 -04.25	N1275801	10	1615105675
DAILIES TOTAL 1 30P 850 141 -03.25	N1275801	17	1615665867
DLY TOTAL 1 MFOCAL 5T 850 141 +01.25 M	N1275809	9	1616250441
DLY TOTAL 1 MFOCAL 5T 850 141 +01.25 M	N1275809	1	1615321321
DLY TOTAL 1 MFOCAL 30P 850 141 +01.25 M		3	1615666372
DLY TTL1 ASTG 30P 860 145 -01.00 075 020	N1275823	3	1617476253
DLY TTL1 ASTG 30P 860 145 +01.50 125 020	N1275997	1	1617356535
DLY TOTAL 1 MFOCAL 30P 850 141 -06.25 L	N1276116	1	1613980785
DAILIES TOTAL 1 90P 850 141 -05.75	N1276224	1	1616792043
DAILIES TOTAL 1 90P 850 141 -04.25	N1276252	12	1615666365
DAILIES TOTAL 1 90P 850 141 -01.75	N1276256	7	1617416804
DAILIES TOTAL 1 30P 850 141 -01.50	N1276269	3	1614885150
DAILIES TOTAL 1 90P 850 141 -03.25	N1276271	62	1615665867
DAILIES TOTAL 1 90P 850 141 -05.75	N1276272	1	1614885150
DAILIES TOTAL 1 90P 850 141 -03.75	N1276273	84	1617416804
DAILIES TOTAL 1 5T 850 141 -05.75	N1276766	4	1615105675
PAILIES TOTAL 1 90P 850 141 -04.25	N1276771	7	1614881416
PAILIES TOTAL 1 90P 850 141 -04.25	N1276789	28	1614814128
	N1276790	56	1614814128
DLY TTL1 ASTG 90P 860 145 -02.25 175 180	N1276866	5	1615112527
LY TTL1 ASTG 30P 860 145 -03.75 075 170	N1276891	1	1614568600
LY TTL1 ASTG 90P 860 145 -05.50 125 180	N1276944	6	1615112527
ALLIES TOTAL 1 90P 850 141 -03.75	N1277291	56	1614814128
AILIES TOTAL 1 90P 850 141 -04.25	N1277293	7	1615105675
LY TOTAL 1 MFOCAL 30P 850 141 -02.00 L	N1277330	1	1614998995
LY TTL1 ASTG 90P 860 145 -01.00 175 180	N1277367	4	1615112527
LY TTL1 ASTG 90P 860 145 -05.50 125 180	N1277449	4	1615112527
OTAL 30 SPHERE 6P 840 142 -03.25	N4159824	1	1613980785
OTAL30 SPHERE 6P 840 142 -03.00	N4159844	1	1614289189
OTAL 30 SPHERE 6P 840 142 -01.75	N4159848	3	1614289189
OTAL30 SPHERE 6P 840 142 -06.00	N4162825	1	1615665862
TAL30 SPHERE 6P 840 142 -06.00	N4162857	1	1615665862



6201 South Freeway Fort Worth, Texas 76134-2099 www.alcon.com

### Actions to take

Alcon asks that you stop distribution of the identified lots of DAILIES TOTAL1® and TOTAL  $30^\$$  and dispose of any remaining product from the identified lots which may remain in your inventory.

To execute this medical device action, please take the following steps:

- 1. Stop any further distribution of product from the identified lots.
- 2. Review your inventory to determine if you have any product from the identified lots within your facility. See **Table 1** for affected DAILIES TOTAL1® and TOTAL 30® lots that have been shipped to your firm.
- 3. Dispose of any product from the identified lots which remains at your facility. If immediate disposal is not feasible, ensure the identified lots are segregated from other products until disposal can be completed.
- Fill out the attached 'Response Form', even if you have zero (0) units remaining in inventory and return the form to Alcon using the contact information provided on the form.
- 5. Forward this notification to others within your organization who may be in possession of product from the identified lots.
- 6. Contact other organizations, eye care providers and/or individuals, whenever this is feasible, to whom you have transferred or distributed the identified lots to advise them of this Voluntary Medical Device Field Safety Corrective Action and request they dispose of contact lenses from the identified lots. For your convenience, a Voluntary Medical Device Field Safety Corrective Action notification template is attached for your use in communicating this issue to your customers.

## For further assistance

Topic	Contact
Questions regarding this Voluntary Medical Device Action including inquiries regarding stock replacement or account credits	Your Alcon account manager or Customer Service
Report an adverse event or product quality issue to Alcon	qa.complaints@alcon.com

Ref. 2024.016 Page 3 of 4



6201 South Freeway Fort Worth, Texas 76134-2099 www.alcon.com

#### **RESPONSE FORM**

# Alcon DAILIES TOTAL1® and TOTAL 30®

MA# 2024.016

OC VISION

To execute this medical device Field Safety Corrective Action, please take the following steps:

- 1. Stop any further distribution of product from the identified lots.
- 2. Review your inventory to determine if you have any product from the identified lots within your facility. See **the table below** for a list of affected DAILIES TOTAL1® lots that have been shipped to your firm.
- Dispose of any product from the identified lots which remains at your facility. If immediate disposal is not feasible, ensure the identified lots are segregated from other products until disposal can be completed.
- Fill out this 'Response Form', including the number of packs discarded for each batch, even
  if you have zero (0) units remaining in inventory and return the form to Alcon using the
  contact information provided below.
- 5. Forward this notification to others within your organization who may be in possession of product from the identified lots.
- Contact other organizations, eye care providers and/or individuals to whom you have transferred or distributed the identified lots to advise them of this Voluntary Medical Device Field Safety Corrective Action and request they dispose of contact lenses from the identified lots.

Product description	Affected lot(s)	Number packs discarded (please complete)
« Material_description »	« Batch_number »	(picase complete)

Return this response form via email to sanja.banek-babic@alcon.com

Your signature below attests that you have read and understood this notice, and that you agree to complete the actions specified herein.

Ciana	A	1	10				
Signa	ture:	1	AM			Date: 11 10 01	20/
		4				13.00.00	14
Printe	ed Name:	,9/	1 /-	0	0	71 10	1.
	- ruanic.	AN	12-17110	1/12	40110		
- C	^		121114	TON 1	1 - 0 29		
Title:	Lein	1/11	0000	-,	11.	A	
	JUMI	ny	Challa	_ 0	VILLE	10 m	
	0	1/					

Ref. 2024.016 Page 4 of 4